	1,	tor Release 2010/08/	05 : ÇIA-RDP80T00	)246A04720044	0001-9
					DR.
INFO		REPORT I		TION R	EPORT
This materi	al contains information affecting	CENTRAL INTELLIG		meening of the Emis	Town Trans
18, U.S.O. S	Secs. 793 and 794, the transmiss	sion or revelation of which in S-E-C-R-	say manner to an una	uthorized person is pi	oblibited by law. 50X1-HUM
COUNTRY	Poland		REPORT		
SUBJECT	Paris Commune Shi	pyard in Gdynia	DATE DISTR.	0 MAri 195	9
			NO. PAGES	1	
			REFERENCES		
DATE OF INFO.					50X1-HUM
PLACE & DATE ACQ.		NS ARE DEFINITIVE. AP			50X1-HUM
		ris Commune Shipya Information on cer lis included in th	tain Polish nava	l vessels und	er
		Information on cer	tain Polish nava	l vessels und	
		Information on cer	tain Polish nava	l vessels und	
		Information on cer	tain Polish nava	l vessels und	
		Information on cer	tain Polish nava	l vessels und	50X1-HUM

S-E-C-R-E-T

STATE X ARMY X MAVY X AIR XFBI AEC (Note: Washington distribution indicated by "X"; Field distribution by "#".)

Orders on hand from the Polish Havy have increased continuously since the fall of 1956. During 1957 and 1958 the largest job for the Polish Mavy has been the repair of the destroyer BLYSKAWICA. This destroyer has been thoroughly rebuilt. The plates have been replaced on almost the entire hull; the bow and stern sections, which were rust-eaten, have been completely rebuilt. Scrapping the vessel was considered because of its condition and the weakness of its construction. After it has been repaired, however, the vessel is to be utilized as a training ship.

Diesel motors are to be installed in the RLYEKAWICA. Since the turbines of the vessel were removed in 1957, it has been found impossible to reinstall them, Poland having no experts on such matters. Experts from Germany considered the cost of reinstalling the turbines too great.

In the fall of 1958, the installation of new guns and torpedo tubes, furnished by the USER, began on the BLYBKAVICA.

The submarine SEP is no longer fit for active duty. At present, the SEP is to a certain extent used as a training vessel, but can no longer be used for diving exercises. The compressor aggregate is not functioning. In May 1957, following repairs, the SEP made a trial run to Hel, during which a diving attempt was made. The submarine went to a depth of 10 meters off the Hel Peninsula, and almost did not come up again. It surfaced with a heavy list.

-1 -

SECRET

93777

50X1-HUM

## SECRET

The submarines KRAKOWNIAK, MAZUR, and KULJAWAK, obtained from the USSR, are repaired and inspected at this shippard.

The whole shippard in Gdynia is divided into various areas, among which the workers are not permitted to circulate without special passes. The shippard guards see to it that the workers do not circulate freely. If a worker is found in an area where he has no work to do and for which he has no pass, he is discharged.

About 4,000 men are employed at the shippard. The office personnel is very numerous in relation to the number of workers.

The workers are divided into so-called "brigades", consisting of from 4 to 10 men. Each brigade is supervised by a "Brigade Chief" (Mistra Brygady), whose next in command is called the "Brigadier" (Brygadzista). The Brigade Chief takes no part in the actual work. His function is to check on the workers and how the work is carried out.

There exists at the yard a very great and severely felt shortage of instruments and tools such as slide rules, micrometers, thread cutting tools, and screws and bolts and monkeywrenches for the motor shop.

The piecework pace is very hard, so that many workers are worn out after 10 or 12 years. The work hours are 0700 to 1500, with a stop for lunch between 1145 and 1200.

The accident rate is very high, due both to insufficient safety measures and carelessness caused by fatigue from overexertion. From the wording of the Polish accident insurance law it is apparent that practically no compensation is paid for absences due to work accidents. The law states that if carelessness was the cause of the accident, and this is ascertained in most cases, the person in question must himself bear all costs.

A mechanic (a diesel motor assembler) receives about 1,400 zloties per month, a brigadier 2,500 zloties, and a brigade chief 3,500 zloties.

50X1-HUM

- 2 -

SECRET

50X1-HUM

